## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3680	DATE	2023/9/28	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd. )			
DESCRIPTION OF DEFECT	On certain C-Class (206 platform control unit might not meet spending on the irreparked vehicle, the on-board-diasensor, even though there is no As a result, the malfunction indictemperature sensor is affected.	m), E-Class (213 platform) vehic cifications. ntensity and duration of solar ra agnosis might erroneously deter defect present. cator light would be illuminated - the limp home mode would be	adiation on the hood of a ct a failure of a temperature and - depending on which e activated without	
DEFECT	In this case, depending on the intensity and duration of solar radiation on the hood of a parked vehicle, the on-board-diagnosis might erroneously detect a failure of a temperature sensor, even though there is no defect present.  As a result, the malfunction indicator light would be illuminated and - depending on which temperature sensor is affected - the limp home mode would be activated without justification. As a result, local legal requirements regarding OBD monitoring and exhaust			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3CA-206004C		2022	3388
	C220d	2023	8
-206004C-		2022	1
3CA-206204C	C220d Wagon	2022	792
		2023	103
3CA-206214C	C220d 4MATIC All-Terrain	2022	836
		2023	38
3CA-213004C	E220d	2022	43
		2023	1
3CA-213204C	E220d Wagon	2022	18
3CA-213217	E220d 4MATIC All-Train	2022	14
		TOTAL	5,242