Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

| Campaign No. | Gai-3673 | Date | Sep. 5, 2023 | |
|-----------------------|--|--|--------------|--|
| Manufacturer | Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited | | | |
| Description of defect | The rear lamp mounted in the body could partially or permanently fail to operate as a result of damage to the rear tail lamp link lead wiring caused by a foam block located adjacent to the lamp on the interior of the body shell. | | | |
| | removed. Inspect th | rehicles will have the foam block mounted in the bodyshell emoved. Inspect the rear tail lamp link lead wiring and the wiring re qualified Not OK the lamp will be replaced. | | |

| Туре | Commercial name | Model year recalled | Number of vehicles |
|-------------|------------------|---------------------|--------------------|
| 3BA-LK9447A | | | 93 |
| 3BA-LKB447A | Range Rover | 2022-2023 | 71 |
| 3CA-LK93WA | | | 117 |
| 3LA-LK934A | Range Rover PHEV | 2023 | 9 |
| 3LA-LKB34A | | | 4 |
| | | 2022-2023 | 294 |

(JIS A4 size)