

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3692	DATE	October 12, 2023
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	It is possible that an electrical connector for the power supply for the fuse carrier in the interior of your vehicle may have not been installed correctly. If this connector were to come loose, it would affect various vehicle functions (such as engine operation, instrument cluster display, lighting). Should this error occur while driving, the engine may switch off. You can steer and brake the vehicle at all times.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-GYDLA	Audi A3 30T	2021-2023	8,131
3BA-GADNFF	Audi SQ2	2022-2023	109
3BA-GADPC	Audi Q2 35T Cod	2021-2023	1,722
3BA-GYDNFF	Audi S3	2021-2023	661
3BA-GYDNNF	Audi A3 40Tq	2021-2023	867
3BA-GYDNWF	Audi RS3	2022-2023	562
3DA-GADFG	Audi Q2 35TDI	2022-2023	878
		Total	12,930