

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3702	DATE	5 <sup>th</sup> Oct 2023
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	An obstruction can change the air pressure arriving at and recorded by the MAP Sensor. The MAP sensor requires accurate manifold air pressure readings in order to send correct information to the ECU. The ECU will adjust the air/fuel ratio based on the data received from the MAP sensor. On defective motorcycles inaccurate MAP data can lead to unstable idle and sometimes an engine stall, increasing the risk of a crash.		

2BL-LUJ660	Trident	2021	699
8BL-LUJ660	Trident	2021-2023	444
	Tiger Sport	2021-2023	273
		TOTAL	1,416