## 第4号様式(英文リコール概要書) (第2関係)

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicies

CAMPAIGN No.	外-3722	DATE	2023/12/1
MANUFACTURER	FENDT (Japanese Importer :MSK Farm Machinery Corporation CEO Takahata Toshinobu)		
DESCRIPTION OF DEFECT	The quality of the accelerator sensor is improper, and it may not be possible to correctly detect the movement of the accelerator pedal.  Therefore, if you continue to use the system as it is, the tractor will not be able to detect the movement of the accelerator pedal while driving, which will make it impossible to control the engine speed, and in the worst case scenario, the tractor may not be able to drive.  We will replace the eccelerator pedal with correct one.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
不明	F724VARIO G6	2021	2
		TOTAL	2

(日本工業規格A列4番)