

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3720	DATE	Nov.21, 2023
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	The fastener that retains the rear shock absorber adjuster on your motorcycle may fracture, potentially allowing the rear shock absorber adjuster to contact the rear tire. A risk of a crash exists if contact between the rear shock absorber adjuster and tire remains undetected, resulting in a loss of pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-STJ	DELUXE	2018 - 2019	138
2BL-STJ	HERITAGE CLASSIC	2018 - 2019	165
8BL-STJ	HERITAGE CLASSIC	2021	167
2BL-STK	HERITAGE CLASSIC S	2018 - 2020	341
8BL-STK	HERITAGE CLASSIC S	2021 - 2023	258
2BL-STK	HERITAGE CLASSIC S ANNIVERSARY	2018	50
8BL-STK	HERITAGE CLASSIC ANNIVERSARY	2023	69
2BL-STK	LOW RIDER S	2020	828
8BL-STK	LOW RIDER S	2021	674
8BL-STZ	LOW RIDER S	2022 - 2023	1010
8BL-STZ	LOW RIDER ST	2022-2023	1461

8BL-STZ	LOW RIDER EL DIABLO	2022	139
		<b>TOTAL</b>	<b>5300</b>