VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3749	DATE	21st Dec 2023	
MANUFACTURE	Triumph Motorcycles Limited			
	(Japanese Importer : Triumph Motorcyces Japan K.K.)			
DESCRIPTION OF				
DEFECT	Due to improper fuse design in electrical equipment, operating the horn while driving may cause the fuse for the starter circuit and horn to blow. As a result, there is a possibility that the horn will not work and the engine will not be able to be restarted.			

2BL-YJJ2500	Rocket3R		392
	Rocket TFC	2019–2023	15
	Rocket 3 GT		93
8BL-YJJ2500	Rocket 3R	2021–2023	33
	Rocket 3 GT	2021–2023	16
		TOTAL	549