

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3728	DATE	December. 8. 2023
MANUFACTURER	HONDA DVLPMT. & MFG. OF AMERICA, LLC		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CAA-NC1	「NSX」	2018 ~ 2019	199
5AA-NC1		2019 ~ 2021	12
		TOTAL	211