

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)****Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3841	Date	July. 30, 2024
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	There is insufficient clamp load on turbocharger oil feed pipe which may, over time, loosen and lead to an oil leak. An oil leak from the turbocharger oil feed pipe may result in oil deposits onto the road surface. This can lead to an increased risk of oil patches on the road surface and potential hazard to other road users.  Repair the oil pipe with additional cramp.		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-DC2NC	F-PACE	2021-2025	403
3CA-DF2NB	E-PACE	2021-2024	332
3CA-JA2ND	XE AWD	2021-2023	78
3CA-JB2ND	XF AWD	2021-2024	106
3CA-JBS2ND	XF Sport Break	2021-2024	32
3CA-LC2ND	Discovery Sport	2021-2024	398
3CA-LY2NAC	RangeRover Velar	2021-2024	289
3CA-LY2NCC		2021-2025	227
3CA-LZ2NB	RangeRover Evoque	2021-2024	924
		2021-2025	2,789

(JIS A4 size)