

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外-3836	DATE	11, July, 2024
MANUFACTURE	Tesla, Inc. (Japanese Importer; Tesla Japan)		
DESCRIPTION OF DEFECT	With regard to the warning device for when the driver's seat belt is not worn, the structural design of the seat occupant sensor was inadequate, so that said warning device may not be activated even when the driver is not wearing the seat belt, thereby failing to meet the criteria for a warning device stipulated in UN-R16 for when the driver's seat belt is not worn.		

TYPE	NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-3L23	Model 3	2018-2020	136
ZAA-3L13		2019-2020	144
ZAA-3L23P		2019	62
ZAA-YL3YB		2020-2023	5
ZAA-YL3YPB		2020	1
ZAA-SLA	Model S	2023	10
ZAA-SLP		2023-2024	26
ZAA-XLA	Model X	2023-2024	14
ZAA-XLP		2023-2024	9
		TOTAL	407