

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	R-3823	DATE	2024/7/5
MANUFACTURE	Hyundai Motor Company (Japanese Importer : Hyundai Mobility Japan)		
DESCRIPTION OF DEFECT	The rear inner shaft is installed without sufficient cooling due to improper maintenance of the heat treatment equipment. As a result, the inner shaft breaks while driving due to insufficient strength, and the ABS and ESC warning lights come on. If you continue driving in this condition, you may become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-NE4LRG	IONIQ5	2023	4
		TOTAL	4

【記入例】

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

輸入車のリコールの場合、**Import** に丸印を記入するか、**Domestic** に二重線を記入又は記載しない用にして下さい。

CAMPAIGN No.	GAI-	DATE	Domestic / Import Vehicles July 21, 2005
MANUFACTURE	(Japanese Importer :)		
DESCRIPTION OF DEFECT	<p>上段には自動車製作者の名称を記載して下さい。 下段には届出者の名称を記載して下さい。</p> <p>日付の記載は、月（英字）日（アラビア数字）、西暦の順でリコール届出年月日を記載して下さい。（リコール開始年月日を記入しないで下さい。）</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		製作年のみの記載。 2005－2006	
		TOTAL	

Domestic Vehicles : 日本国内車両

Import Vehicles : 輸入車両

CAMPAIGN No. : 届出番号

DATE : 届出年月日

MANUFACTURE : 製作者名

DESCRIPTION OF DEFECT : 不適合状態

TYPE : 型式

COMMERCIAL NAME : 通称名

MODEL YEAR RECALLED : 対象車両の製作年

NUMBER OF VEHICLE : 対象車両数