

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3873	DATE	September. 19. 2024
MANUFACTURER	Thai Honda Co., Ltd.		
DESCRIPTION OF DEFECT	When one of the rear direction indicator lamps fails due to the inappropriate internal circuit of the relay that controls direction indicator lamps, turning the switch of the rear direction indicator lamp on the failed side first and then on the other side may cause the front and rear direction indicator lamps on the non-failed side flash quickly. For this reason, the technical requirements in UN Regulation No. 53 (Addenda to the 1958 Agreement) are not fulfilled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BJ-JC91	「CB125R」	2024	183
TOTAL			183