

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外-3874	DATE	10, Sept, 2024
MANUFACTURE	Tesla, Inc. (Japanese Importer; Tesla Japan)		
DESCRIPTION OF DEFECT	Due to inadequate software design for the camera mounted on the vehicle B-pillar, the sensor does not detect the inability to detect when the camera becomes undetectable due to dirt, etc. As a result, the driver is not alerted to the malfunction and the criteria for steering devices are not met.		

TYPE	NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-3L13T	Model 3	2023-2024	1417
ZAA-3L23T		2023-2024	1024
ZAA-3L24PT		2024	236
ZAA-YL1YT	Model Y	2024	772
ZAA-YL3YT		2024	363
ZAA-YL3YPT		2024	56
ZAA-SLP	Model S	2022-2024	129
ZAA-SLA		2023-2024	95
ZAA-XLP	Model X	2022-2024	84
ZAA-XLA		2023-2024	212
		TOTAL	4388