VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3863	DATE	September. 2 nd , 2024	
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION OF DEFECT	Due to software error in the RAM, in very rare cases, a communication fault can occur in the CAN bus during vehicle start-up in combination with the RAM control unit start-up. In the event of a fault, the outside sound is not played back. The "acoustic pedestrian protection failed" CCM is not activated. Vehicle occupants will scarcely detect acoustically that there is a fault. The fault pattern will heal itself with the next life cycle but may recur afterwards.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-32FK45	BMW i5 eDrive40	2023	61
ZAA-42FK89	BMW i5 M60 xDrive	2023	15
		TOTAL	76