

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3895	DATE	October. 31. 2024
MANUFACTURER	Honda Vietnam Co., Ltd.		
DESCRIPTION OF DEFECT	As for the motor, due to the inappropriate management method in the process of manufacturing the crankcase and the gearbox casing, both cases may not adhere to each other tightly enough, causing a transmission oil leakage. For this reason, poor oil lubrication may make an odd noise and if it continues to be used, a bearing inside one of the cases may be damaged and in the worst case, the rear wheel may be locked up while running, becoming unable to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-AF75	「TACT」	2014～2015	37,773
JBH-AF74	「Dunk」	2013～2015	13,720
TOTAL			51,493