

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3887	DATE	October. 28 th , 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a manufacturing defect, the bypass flap bolts on the exhaust gas recirculator (EGR) module may not have been correctly tightened. Therefore, there is a possibility that the bolt will loosen, and in this case the MIL may light on which would not comply with the Japanese safety regulation/standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-JU8230A	BMW X5 xDrive 35d	2023	39
3CA-12EY30S	BMW X6 xDrive35d	2023	41
3CA-22EN30	BMW X7 xDrive40d	2022 - 2023	661
3CA-22EJ30	BMW 740d xDrive	2022 - 2023	301
		TOTAL	1,042