

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3845	DATE	15 th October, 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a manufacturing defect, the coupling rod of the exhaust gas recirculation module may break. Therefore, valve flaps cannot be switched, and the motor control activates a fault mode where the EGR is deactivated. The MIL is activated, and it may happen that the exhaust gas limits are exceeded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-UZ7230	BMW X3 M40d	2022 - 2023	339
3CA-JU8230A	BMW X5 xDrive35d	2022	1
	BMW X5 xDrive 40d	2022 - 2023	693
3CA-JU8230S	BMW X5 xDrive35d	2022 - 2023	14
3CA-GT8230S	BMW X6 xDrive 35d	2022 - 2023	258
TOTAL			1305