

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3886	DATE	October. 10. 2024
MANUFACTURER	HONDA AUTOMOBILE(THAILAND)CO., LTD. HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for some hybrid vehicles, due to the inappropriate working process of the high-pressure fuel pump components, metallic powder created in the process may get stuck between the pump component and the working jig. This could cause a crack on the end of the worked part and the continuation of use may make the crack completely run through due to the oscillation of the operating pump, resulting in a fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-CY2	「ACCORD」	2023～2024	2,723
TOTAL			2,723