

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3888	DATE	December 9 th , 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to insufficient strength of the bolts in the adjustment units of the variable valve timing system on the intake and exhaust side, the bolts may break. Therefore, the system does not operate properly, the engine warning light is turned on, and in the worst case, there is a risk that the engine will stop while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-UD30	「BMW 130i」	2009 - 2011	134
ABA-UC30	「BMW 135i Coupe」	2010 - 2011	2
ABA-VB25	「BMW 325i」	2010	2
ABA-VS25	「BMW 325i Touring」	2010	4
ABA-VF25	「BMW 325Xi」	2009 - 2010	3
ABA-DX35	「BMW 335i Cabriolet」	2010	1
DBA-FP25	「BMW 523i」	2010 - 2011	3,156
DBA-MT25	「BMW 523i Touring」	2010 - 2011	1,166
ABA-NU25	「BMW 525i」	2009	236
ABA-PU25	「BMW 525i Touring」	2009 - 2010	61
DBA-FR30	「BMW 528i」	2010 - 2011	2,313
DBA-MU30	「BMW 528i Touring」	2010 - 2011	690
ABA-NU30	「BMW 530i」	2009	6
ABA-PU30	「BMW 530i Touring」	2009 - 2010	3
ABA-PV30	「BMW 530Xi Touring」	2009	1
CBA-FR35	「BMW 535i」	2010	1
DBA-FR35	「BMW 535i」	2010 - 2011	3
CBA-SN30	「BMW 535i Gran Turismo」	2010	2
ABA-EH30	「BMW 630i」	2009 - 2010	3
DBA-LW30	「BMW 640i Cabriolet」	2010	1
DBA-LW30C	「BMW 640i Coupe」	2011	1
ABA-VL25	「BMW X1 xDrive25i」	2010 - 2011	992
ABA-PC25	「BMW X3 2.5Si」	2009 - 2010	22
ABA-PC30	「BMW X3 3.0Si」	2009 - 2010	2
CBA-WX30	「BMW X3 xDrive28i」	2010 - 2011	342
ABA-FE30	「BMW X5 3.0 si」	2009 - 2010	46
ABA-ZV30S	「BMW X5 xDrive35i」	2010	1
ABA-LM25	「BMW Z4 sDrive 23i」	2009 - 2011	1,338
		TOTAL	10,532