

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3947	Date	February 27, 2025
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	<p>There is a possibility that, because the design of the outer door handles is improper, humidity could get into the electronics of the outer door handles through the gap in the membrane filter. Therefore, a short circuit occurs in the electronic circuit, and an incorrect signal is output to the door control unit. At vehicle speeds of below 15 km/h lead to a vehicle door unexpectedly opening if the vehicle is subject to high lateral forces.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-E2EBJ	ID.4	2022-2023	3,613
		Total	3,613