

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|--|------|---------------|
| CAMPAIGN No. | gai-3940 | DATE | 21, Feb, 2025 |
| MANUFACTURE | Tesla, Inc. (Japanese Importer; Tesla Japan) | | |
| DESCRIPTION OF DEFECT | Due to inadequate software design, the control ECU board may short-circuit due to reverse current when the vehicle power is turned on. As a result, the function of the rear-view camera may be lost, and the device may not meet the criteria for a rear-view camera. | | |

| TYPE | NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|---------|---------------------|-------------------|
| ZAA-3L13T | Model 3 | 2024 | 486 |
| ZAA-3L23T | | 2024 | 356 |
| ZAA-3L24PT | | 2024 | 172 |
| ZAA-YL1YT | Model Y | 2024 | 1169 |
| ZAA-YL3YT | | 2024 | 328 |
| ZAA-YL3YPT | | 2024 | 48 |
| ZAA-SLP | Model S | 2024 | 6 |
| ZAA-SLA | | 2024 | 4 |
| ZAA-XLP | Model X | 2024 | 24 |
| ZAA-XLA | | 2024 | 5 |
| | | TOTAL | 2598 |