

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3973	DATE	March. 27. 2025
MANUFACTURER	Thai Honda Co., Ltd.		
DESCRIPTION OF DEFECT	As for the motor, the oil pump driven gear may be tilted due to inappropriate material and molding of the driven gear. In addition, the tooth surface of the drive gear may be rough in some cases. As a result, there is a risk of the driven gear wearing and making abnormal noise when the gears mesh. If the motor is continued to be used in this state, the gears may break and the oil pressure may drop; and in the worst case, the engine may stop while driving, rendering the vehicle inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BK-KF54	「ADV160」	2022～2024	7,031
TOTAL			7,031

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS
GEAR, OIL PUMP DRIVEN	15133-K2S-N00	2023～2025	309
TOTAL			309