

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|---|------|---------------|
| CAMPAIGN No. | GAI-3960 | DATE | March 6, 2025 |
| MANUFACTURER | Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.) | | |
| DESCRIPTION OF DEFECT | For the engine control unit, due to sub-optimal configuration of the OBD (On Board Diagnostics) system, the crankshaft position component may not be monitored correctly under at cold engine conditions and at engine speeds higher than 2.500 rpm. Consequently, it will lead to a limited misfire detection capability and an emission control system warning light (MIL) will not illuminate. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-------------------------------|---------------------|-------------------|
| 3AA-F2DJPA | Audi RS7 SB Air-suspension | 2021-2023 | 80 |
| 3AA-F2DJPF | Audi RS6 Avant | 2021-2023 | 104 |
| 3AA-F2DJPL | Audi RS6 Avant Air-suspension | 2021-2023 | 109 |
| 3AA-F2DJPS | Audi RS7 SB | 2021-2022 | 82 |
| 3AA-F8CWWF | Audi S8 | 2020-2021 | 143 |
| 3AA-F8CXYP | Audi A8 60Tq | 2021 | 16 |
| 3AA-F8CXYL | Audi A8L 60Tq | 2021 | 15 |
| AAA-F8CXYP | Audi A8 60Tq | 2018-2020 | 376 |
| AAA-F8CXYL | Audi A8L 60Tq | 2018-2020 | 71 |
| | | Total | 996 |