

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3971	DATE	24 <sup>th</sup> Apr, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On affected vehicles, the 12V inverter supply line may have been damaged during the assembly process. The supply line was jammed between the transmission holder and the cable holder/strain relief when it was screwed in. In case of a severed line, the driver will be warned by a Check Control Message and a warning lamp. If it is severed, this could lead to stalling, which could only happen during a purely electric journey.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-42EU30	「BMW X5 xDrive 50e」	2023	27