

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**

**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3989	Date	Apr. 22, 2025
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	<p>There is insufficient clamp load on turbocharger oil feed pipe which may, over time, loosen and lead to an oil leak. An oil leak from the turbocharger oil feed pipe may result in oil deposits onto the road surface. This can lead to an increased risk of oil patches on the road surface and potential hazard to other road users.</p> <p>Repair the oil pipe with additional cramp.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-DC2NC	F-PACE	2024-2025	42
3CA-DF2NB	E-PACE	2024	39
3CA-LC2ND	Discovery Sport	2024	71
3CA-LY2NAC	RangeRover Velar	2024-2025	87
3CA-LY2NCC		2024-2025	34
3CA-LZ2NB	RangeRover Evoque	2024-2024	289
		2024-2025	562

(JIS A4 size)