

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3979	DATE	April. 3. 2025
MANUFACTURER	Thai Honda Co., Ltd.		
DESCRIPTION OF DEFECT	For some headlamps, due to inappropriate routing of the wiring that connects among circuit boards, the wiring interferes with peripheral parts. For this reason, the core cable connected with a circuit board may be cut because of vibration created by the running vehicle, causing the headlamps to start flickering, and in the worst case, the headlamps may not be turned on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MC52	「CB250R」	2018～2022	9,284
8BK-MC52		2022～2024	4,560
2BJ-JC79	「CB125R」	2017～2020	3,040
8BJ-JC91		2021～2024	3,520
		TOTAL	20,404

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS	NOTE
HEAD LIGHT ASSY	33100-K94-T02	2018～2025	151	「CB250R」 「CB125R」
TOTAL			151	