

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

| | | | |
|-----------------------|--|------|--------------|
| CAMPAIGN No. | Gai-3927 | DATE | May 12, 2025 |
| MANUFACTURE | BYD Company Limited (Japanese Importer : BYD Auto Japan Inc.) | | |
| DESCRIPTION OF DEFECT | In the waist seatbelt pretensioners provided in the driver's and front passenger's lower seats, the wiring fixing method is inappropriate, resulting in poor contact with the waist seatbelt pretensioner wiring connector, which may cause the SRS warning light to illuminate. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------|-----------------|---------------------|-------------------|
| BYD | DOLPHIN | 2023 - 2024 | 713 |
| | | TOTAL | 713 |