

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4043	DATE	July. 17. 2025
MANUFACTURER	Wuyang Honda		
DESCRIPTION OF DEFECT	<p>As for electric wiring, sometimes the main harness has weld spatter* remaining on the cable routing sections due to inappropriate weld spatter removal instructions during frame welding. This would make the spatter interfere with the said harness, and if the vehicle continued to be used, the cable sheath would be worn and the core would be exposed to cause short circuit, which has the risk of malfunction of the head lamps, the direction indicators, the speedometer, etc., and/or the vehicle becoming undrivable.</p> <p>Spatter*: Metallic particles and the like produced during a welding process attached to a frame</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAD-EF12	「Benly e II MD」	2019～2024	17,467
ZAD-EF09	「Benly e I MD」	2020～2023	3,076
ZAD-EF07	「Benly e I 」	2019～2023	889
ZAD-EF08	「Benly e I PRO」	2019～2024	220
ZAD-EF10	「Benly e II 」	2019～2023	103
ZAD-EF11	「Benly e II PRO」	2019～2024	72
TOTAL			21,827