VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	外-4053	DATE	August 1. 2025			
MANUFACTURER	JOHN DEERE (Japanese importer:YANMAR AGRIBUSINESS CO.,LTD.)					
DESCRIPTION OF DEFECT	Due to an improper manufacturing process, some of the fasten bolts for the four—wheel drive shafts of agricultural tractors hat insufficient tightening torque. As a result, if continued use is continued in this condition, to fastening bolts will loosen, and in the worst case scenario, to fastening bolts may fall off, causing the four—wheel drive shaft become dislodged and interfere with the shaft cover, resulting abnormal noise.					

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE	
_	JD-6R185	2024		1	
		TOTAL	1		