

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

Campaign No.	Gai-4069	Date	8 September, 2025
Manufacturer	Liuzhou Wuling New Energy Automobile Co., Ltd. (Japanese Importer: ASF Inc.)		
Description of defect	A brake hose fitted between the brake fluid reservoir tank and the brake master cylinder may have been assembled with an incorrect part due to inappropriate manufacturing instructions and may undergo chemical reactions with the brake fluid inside the hose during use. Furthermore, the brake fluid eluted by the chemical reaction may cause a chemical reaction with the cups in the brake master cylinder, resulting in deterioration of the cups. When the brake pedal is continuously at low speed, the hydraulic pressure in the brake master cylinder may decrease resulting in reduced braking force.		

Type	Commercial Name	Model Year Recalled	Number of Vehicle
-	-	2024	70
		Total	70