

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4093	DATE	October. 9. 2025
MANUFACTURER	Wuyang Honda Motors (Guangzhou) Co., Ltd.		
DESCRIPTION OF DEFECT	As for electric wiring, sometimes the main harness has weld spatter* remaining on the cable routing sections due to inappropriate weld spatter removal instructions during frame welding. This would make the spatter interfere with the said harness, and if the vehicle continued to be used, the cable sheath would be worn and the core would be exposed to cause short circuit, which has the risk of malfunction of the head lamps, the direction indicators, the speedometer, etc., and/or the vehicle becoming undrivable. Spatter*: Metallic particles and the like produced during a welding process attached to a frame		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAD-EF07	「Benly e I 」	2023	3
		TOTAL	3