

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4076	DATE	8 th Oct. 2025
MANUFACTURE	Tesla, Inc. (Japanese Importer; Tesla Japan)		
DESCRIPTION OF DEFECT	"In the right-side body controller module, due to insufficient design review, there is an inappropriate control program for the driver's side power window. As a result, when fingers are caught, there is a possibility that the anti-pinch function may not operate properly, potentially failing to comply with safety standards."		
YPE	NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-YL1YT	Model Y	2025	1,108
ZAA-YL3YT			854
		TOTAL	1,962