

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4123	DATE	December 04, 2025
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	The Tire Pressure Monitoring System (TPMS) antenna cable may have been built with the cable pinched under the left rear seat belt retractor bracket, which may result in the TPMS unable to detect low tire pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-JL20L	「Wrangler Unlimited」	2025	579
		TOTAL	579