

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4125	DATE	4 th Dec, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>Due to an assembly error, the threaded connection of the oil pump was not carried out correctly. If the threaded connection is not carried out correctly, the screw might come loose during operation. This may cause insufficient oil supply to the engine, followed by displaying a check control message and noise. Continuing to drive in this condition may possibly resulting in engine damage and in the worst case scenario, the engine may stall while driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-AE44M	BMW M8 Cabriolet	2024	1