

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai – 4161	DATE	17 March 2026
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to improper manufacturing processes, some of the wiring installed beneath the driver's and front passenger's seats may not be routed correctly. As a result, the wiring may become damaged when the seats are adjusted, causing the airbag warning light to illuminate. In the worst case, the side airbags may fail to deploy properly in a collision, increasing the risk of serious injury to the occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-J1SR	Taycan Turbo GT	2024~2025	39
		Total	39