

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4159	DATE	March. 12. 2026
MANUFACTURER	Thai Honda Co., Ltd.		
DESCRIPTION OF DEFECT	In the locking mechanism, the bolt that secures the steering lock may sometimes be insufficiently tightened due to improper tightening. For this reason, if the vehicle continues to be operated without corrective action, the bolt may loosen, and the steering wheel may not be locked when the vehicle is stopped. Also, if the bolt falls off and becomes caught in the frame, in the worst-case scenario, steering may become inoperative, which can cause the vehicle to tip over.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BK-MC49	「Rebel 250」	2022～2025	22,666
8BK-MC57	「CL250」	2023～2025	8,804
TOTAL			31,470