

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-4170	DATE	06.04.2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>On affected vehicles, the cockpit wiring harness on the air conditioning unit was fixed very close to a screw connection on the interior microfilter housing cover. It cannot be ruled out that cables may be damaged when replacing the microfilter during workshop visit.</p> <p>Damaged cables can lead to malfunctions of the air conditioning system as well as to a short circuit. In the event of a short circuit, a sensor may overheat while the vehicle is in operation. As a result, smoke may develop from the instrument panel and, subsequently, a fire cannot be ruled out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-12GV20	「BMW 523i Touring」	2024-2025	51
3CA-22FL20	「BMW 523d xDrive」	2023-2025	1,091
3AA-12FJ20	「BMW 523i」	2023-2025	1,282
3CA-22GW20	「BMW 523d xDrive Touring」	2024-2025	1,106
3AA-12FM20	「BMW 525Li」	2024-2025	171
ZAA-32FK45	「BMW i5 eDrive40」	2023-2025	389
ZAA-12HH45	「BMW i5 eDrive40 Touring」	2024-2025	192
ZAA-42FK89	「BMW i5 M60 xDrive」	2023-2025	116
ZAA-32HH89	「BMW i5 M60 xDrive Touring」	2024-2025	30
3AA-22EH30	「BMW 740i」	2022-2025	721
3CA-22EJ30	「BMW 740d xDrive」	2022-2025	585
ZAA-42EJ49	「BMW i7 eDrive50」	2023-2025	188

ZAA-52EJ89	「BMW i7 xDrive60」	2022-2024	383
ZAA-82EH93	「BMW i7 M70 xDrive」	2023-2025	87
3LA-82GV44	「BMW M5 Touring」	2025	60
3LA-82FK44	「BMW M5」	2024-2025	211
		TOTAL	6,663