

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4197	DATE	June. 4. 2026
MANUFACTURER	HONDA DVLPMT. & MFG. OF AMERICA, LLC		
DESCRIPTION OF DEFECT	In an emergency flat tire repair kit, the inappropriate structure of the fitting of the emergency repair hose and inappropriate opening pressure adjustment of the pressure relief valve may cause excessive pressure applied inside the tire sealant bottle when repairing a flat tire without the hose correctly connected. For this reason, once the pressure inside the bottle exceeds the pressure limit during use or storage after use, the tire sealant bottle may get damaged, scattering the components, which has a risk of injuring the user in the worst case scenario.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZBA-ZC8	「CR-V」	2024～2026	118
		TOTAL	118