

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-4120	DATE	Jul 30, 2026
MANUFACTURE	SCANIA CV AB (Japanese Importer: SCANIA JAPANA Co. Ltd.)		
DESCRIPTION OF DEFECT	Due to improper wiring instructions during body-building operations, the power supply circuit for the side turn signal indicator was connected directly from the up-fitting console instead of being routed through the Up-fitting Central Electric Unit. As a result, when a front or rear turn signal indicator becomes inoperative, the driver warning function fails to operate as intended, and the vehicle does not comply with the relevant safety requirements.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2017 - 2025	509
		TOTAL	509