

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	Gai-4202	DATE	July. 8th 2026
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	A blocked breather port can result in pressure build-up in the crankcase. If the dipstick is removed while the crankcase is pressurized, and the pressure is not slowly released before removing the dipstick, oil may be discharged from the fill spout, creating a risk of injury		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-FL7	ROAD GLIDE	2024-2025	863
8BL-FL7	STREET GLIDE	2024-2025	494
8BL-FL7	STREET GLIDE ULTRA	2025	70
8BL-TGN	STREET GLIDE 3 LIMITED	2026	37
8BL-TGN	ROAD GLIDE 3	2026	19
8BL-ST9	BREAKOUT	2025	2
8BL-ST9	FAT BOY	2025	89
		TOTAL	1574