

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5156	DATE	June 2 ,2022
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In certain buses, the battery cables are damaged because terminal crimping work in the manufacturing process was conducted inappropriately. Therefore, if the cables are used continuously without repair, they may break, and eventually the engine may not be restarted.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-LV290N3 2RG-LV290N3 2TG-LV290N3	[ERGA]	2021-2022	75
2RG-LV290Q3 2TG-LV290Q3		2021-2022	16
2KG-LR290J4	[ERGA MIO]	2021-2022	69
		TOTAL	160

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Battery Cable	4-63361021-1 4-63361344-0 4-63361729-2 4-63361730-0	2021	8
		TOTAL	8