

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5157	DATE	Jun. 2. 2022
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In certain buses, the battery cables are damaged because terminal crimping work in the manufacturing process was conducted inappropriately. Therefore, if the cables are used continuously without repair, they may break, and eventually the engine may not be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-KR290J4	[HINO Rainbow]	2021	29
2KG-KV290N3	[HINO BlueRibbon]	2021~2022	14
2TG-KV290N3			
2RG-KV290Q3		2021~2022	8
2TG-KV290Q3			
		TOTAL	51

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
battery cable	46336-17292A	2021	1
	46336-17292B	2021	1
	46336-20411F	2021	1
		TOTAL	3