

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5158	DATE	Jun. 2 , 2022
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The select cable of the manual transmission may come contact with the fuel hose, due to the improper shape of the select cable mount bracket.</p> <p>If the vehicle is being used in such condition, the fuel hose may be damaged and the fuel may leak in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BD-DA17V	EVERY	2022	38	M/T vehicles only
		TOTAL	38	