

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5159	DATE	June. 2. 2022
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JF3	「N-BOX」 「N-BOX Custom」	2018	143,739
DBA-JH1	「N-WGN」 「N-WGN CUSTOM」	2018	31,328
DBA-JH2		2018	8,137
HBD-JJ1	「N-VAN」	2018	18,719
DBA-JG1	「N-ONE」	2018	9,568
DBA-JG2		2018	1,547
DBA-JF1	「N-BOX SLASH」	2018	3,599
DBA-JF2		2018	626
DBA-JW5	「S660」	2018	2,360
		TOTAL	219,623