

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 1 6 4	DATE	June.9th.2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the rear axle, the rear axle bolt connecting rear wheel hub may be loosen and cause abnormal noise by rattling compornent parts due to inappropriete tihtening operation . If continue to be driven on this conditon, in worst case, the wheel may be locked in case of interference between axle bolt and the hub.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-P 1 5	KICKS	2 0 2 0 ~ 2 0 2 1	4, 7 3 6
		TOTAL	4, 7 3 6