

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5166	DATE	Jun.14 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large-sized route buses or the like, the turnbuckle attached to the upper part of the glide slide door at the front entrance is not strong enough, and the turnbuckle may crack. If the vehicle continues to be used in this condition, the turnbuckle may break, making it impossible to open and close the door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-MP38FK	「FUSO AERO STAR」	2014~2017	838
QKG-MP38FM		2014~2017	326
2KG-MP38FK		2017~2021	119
2KG-MP38FM		2017~2021	86
2PG-MP38FK		2017~2021	1,027
2PG-MP38FM		2017~2021	214
			TOTAL