

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5170	DATE	June. 23. 2022
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In vehicles with manual transmission where the ignition timing control program of the engine control computer is inadequate, ignition timing may be delayed if the clutch lever is kept in a small grip range with the throttle closed. As a result, the engine may stall due to low rpm.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-SC79	「Gold Wing」 「Gold Wing Tour」	2019～2020	62
		TOTAL	62