

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5177	DATE	Jun.23.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the hub bolts for mounting tire of the subject vehicles, the bolts could become loosen due to repeated sudden turning and/or braking. If the vehicle continues to be operated in this condition, abnormal noise could occur, and in the worst case, tire could separate from the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-XEAM10	[bZ4X]	2022	42
ZAA-YEAM15			70
ZAA-XEAM10X	[SOLTERRA]		10
ZAA-YEAM15X			82
		TOTAL	204