

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 1 7 1	DATE	June. 30th. 2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Regarding rear right brake hose bracket, the bracket welding with the body side member was poor welding due to inappropriate welding operation and the welding may be removed by running vibration, and then abnormal noise will be caused by interference between brake pipe and body side member.</p> <p>If continue to drive in this condition, the brake pipe may be damaged and the brake fluid may leak, in worst case, one out of two brake systems will fail and stopping distance may be increased.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
5AA-GFNC27	N I S S A N S E R E N A	2 0 2 1 ~ 2 0 2 2	5 0 2
5AA-GNC27			3 0 3
5AA-SGNC27	S U Z U K I L A N D Y		1 9
		TOTAL	8 2 4