## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5174	DATE	June 30, 2022
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to an inappropriate control program in the navigation system, #1. When the navigation is started, information processing in the system may not complete and the navigation may keep rebooting.  #2. The system recovery is not processed when the communication is discontinued due to some factors such as power fluctuation. In this case, the image from the camera may not appear on the display and a black screen may be displayed.		
	the area in from	nt and to the left side of screen, and this may ricles, Article 44 (Star	e images from the camera to check f a vehicle are not displayed on the not conform to Safety Regulations adard for Rear-View Mirror and

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2021~2022	#1 3,007 #2 7,812
		TOTAL	7,812